SOUTH PRODUCTION NOTES

September 21, 2014
Afternoon Shift

BASF EMPLOYEES
83 Last Recordable
444 Last Lost Time

Continue to Record Fines on Green Sheet

#1 MED / AI-4190:

Make 2 batches and take samples to the lab to be tested on Saturday morning. Midnight shift: Per Kirk, the earliest we can have someone work on #1 dryer gas valve is Sunday morning (Dave Crissman from IMC). Unless someone available to work this sooner, we will hold until Sunday.

Day shift: Still down-IMC addressing issues.

Afternoon shift:

#1 RC / Maintenance work:

Down-Work scheduled on calciner the weeks of 9/22 and 9/29.

Midnight shift: Down

Day shift: Down Afternoon shift:

Exhaust to

#2 MED line / Cu-0860:

Continue. Add in the wet mix. Continue with the Bindzil 2034, SAP # 50363317).

Midnight shift: Continue Day Shift: Continued.

Afternoon Shift:

#2 RC/ Cu-0860:

Continue to feed the calciner.
Midnight Shift: Continue
Day Shift: Continued.
Afternoon shift:

Exhaust to F1

#3 MED / D-1794:

Continue On. Continue. Add in the wet mix from the cart and any drums as we go.

Grease the end seals once a shift. Lot 42/Bags 7-9 will be remade at end of run-B Grodecki.

Midnight Shift: Continue Day shift: Continued.

Afternoon Shift:

#3 RC / D-1794:

Continue when feed is available.

Midnight shift: Continued for most of night, stopping feed to calciner (last bag,

build feed) Day shift:

Afternoon Shift:

Need to exhaust to CTO

New Pfaudler / D-1145 SNAP/V-2045 Next:

Done. All carts are cleaned and taken back to the harrop kiln storage area.

Midnight shift: Cleaning pfaudler

Day shift: No activity.

Afternoon Shift:

National Dryer / D-1145 SNAP:

Will need to vacuum the dryer in preparation for soda blasting Monday.

Midnight Shift: No activity. Will finish clean-up later Sunday for Monday soda blasting

Day shift: Need to finish cleaning today.

Afternoon Shift:

#4 RC / D-1145 SNAP:

Completed/ Need to clean entrance and discharge to inspect calciner.

Midnight Shift: Suntron pulled and tube entrance looks pretty dirty (green chrome ring). Will need to discuss with production team on moving forward (clean, or pull tube and replace)

Day shift: No activity.

Afternoon Shift:

Exhaust to 4A DC

#5 RC / Cu-3818:

Continue to feed. W.O.W. for inspection of the 5A roto-lock (possibly worn paddles). (RS 9/8/14) – When run is complete. Hold for instructions from Bodmann. Cu 3818 should be next. Copper Carbonate-do not use World Metals.

Midnight Shift: Continue Day shift: Continued.

Afternoon shift:

Exhaust to 5A DC Abbe Blender / 5206:

ONLY run Abbe on off shifts and weekends.

Midnight shift: Continue. Several empty buggies remain. Need dryer repaired

to continue Day shift:

Afternoon Shift:

#6 RC / D-5206

Continue when we have feed and can run the Abbe.

Midnight shift: No activity as dryer would not stay lit. IMC arriving Sunday morning to work on #1 dryer...will have them look at #6 as well.

Day Shift:

Afternoon shift:

Exhaust to Sly Scrubber

Tower 3 / Cu-1986:

Continue On. Tower 3 will be unloaded if we have enough line space and will need washed out.

Midnight Shift: Hold

Day shift:

Afternoon shift:

Tower 6 / Cu-0860:

Continue on. Will hold until we get more drum liners in.

Midnight Shift: Hold

Day shift:

Afternoon shift:

North Screener / Cu-1986:

Continue On.

Midnight shift: Hold...waiting for drum liners

Day shift:

Afternoon shift:

South Screener / Cu 0860:

Continue On.

Midnight shift: Hold...waiting for drum liners

Day shift:

Afternoon Shift:

#2662 (west) Pill Machine / Al-3915 T 5/32:

Midnight shift: Continue Day Shift: Continued.

Afternoon shift:

#2664 (east) Pill Machine / Al-3915 T 5/32:

Midnight shift: Continue Day shift: Continued.

Afternoon shift:

Old Pfaudler / Clean for D-1795:

Hold, D-1795 impregs coming soon

Midnight Shift: Hold Day Shift: Hold

Afternoon shift: Hold

PK Blender / Selexsorb next:

We are going to start making the Selexsorb. Weigh all the bags off the PK.19 of 25 batches made of 3915 pill mix-we will make later, DC bag-house pressure drop issues are resolved-monitor.

Midnight Shift: Continue Day shift: Continued.

Afternoon shift:

TK #2 / V-2010:

NOTE: all tunnel kiln personnel need to remove their belongings from their respective TK Racal lockers. Chuck Evans will have new Racal/PAPR lockers assigned to TK operators by the PPE shelves in building 17. See Chuck or your GL for details.

Midnight shift: Continue. Was advised that drum #18 had oxidized interior (rust). Pics taken and sent to Bill Grodecki...waiting for his instructions regarding this drum.

Day Shift: Continued.

Afternoon shift:

TK #4 / Cu 0540 next (Sterotex screening for now):

This kiln is off.

Midnight shift: No activity

Day Shift:

Afternoon shift:

Building 27 Belt Filter / S1-81 trial:

No activity. The ceilings in building 27 will be painted next week everywhere but the horne machine area.

Midnight shift: No activity. Will continue moving stuff on day shift Day shift: No activity-finished clean up for painting on Monday.

Afternoon Shift:

Priorities 1 through 10 are basically all the same priority, should be considered urgent and will require call outs for maint. issues and/or processing issues.

- 1) Reduction Towers
- 2) Reduction Tower Screeners (if liners arrive)
- 3) #3 Line/#3RC
- 4) South PK
- 5) #1 Line
- 6) #2 Line/#2RC
- 7) #5 RC
- 8) West Pfaudler clean up & V-2045 soln make up
- 9) #4 RC, Clean up for Selexsorb AS
- 10) Horne Tabletting
- 11) Abbe/#6RC

To-Do items:

Cu-0860 inserts can be placed in the oven in B-31 lab for 2 hours then poke out inserts with paperclip-per Bob Priscak. (keep working on these)

Monday, 9/22/14, they will be painting the ceiling/walls in Building 27. They will start by Tank 107.